


Overview of assembly locations for mounting kit for M RCK wiring loom


6111B025A00




Mounting location for bracket number 1:




Mounting location for bracket number 2:



Mounting location for bracket number 3:




Mounting location for bracket number 4:



Mounting location for bracket number 5:

Lambda 2 sensor



Mounting location for bracket number 6:

Fast shift sensor

